

JACDEC's FACTSHEET / ACCIDENT + STATISTICAL INFORMATION 1

06. June 2009 Myanmar Airways Fokker 28-4000 XY-ADW

Sittwe Airport, Myanmar (Burma)



preliminary data as of 19-06-2009

DATE:	06.06.2009	Local Time:	~08:30				
LOCATION:	Sittwe-International Airport	4-Letter Code:	VYSW	Country:	Myanmar (Burma)	Region:	Mid-East Asia
OPERATOR:	Myanma Airways, UB / UBA [http://www.mot.gov.mm/ma/index.html]			Operational Base:	Yangon-Intl Airport, Myanmar (Burma)		
TYPE:	Fokker 28-4000	Registration:	XY-ADW	Constr.No.:	11114	Age:	32 y + 2 m
OPERATION:	DSP	Flight No.:	UB 409	From:	Yangon	To:	Sittwe
OCCUPANTS:	64 pax + 4 crew	Fatalities:	0 pax	0 crew	0 other	Damage To Aircraft:	
Details:		Injuries:	1 pax	2 crew	0 other	damaged beyond repair	

On landing at Sittwe, the aircraft ran off the end of the runway coming to rest on soft ground. Three people, among them one of the pilots were injured. The aircraft suffered severe damage to its wings - most severely to its right wing - and forward fuselage when it hit trees before it came to rest minus its landing gear. Due to stress to the airframe, a number of exits won't open resulting in many passengers getting stuck before all escaped via the emergency doors. The only runway at Sittwe (11 /29) is 1.829 meters in length. According to an analysis by US Defense NOTAM Service, the usable runway length at Sittwe is only 1.340 meters, also, parts of the runway lighting is considered unserviceable.

Photo(s) (R. Wallner, The Irrawaddy)



STATISTICAL INFORMATION

30th hull loss for Myanmar Airways

166th hull loss of a Fokker 28

2nd hull loss at Sittwe Airport

TYPE STATISTICS: Fokker 28

Total aircraft built:	245
No. of hull losses:	44
No. of fatalities:	769 (incl. actual case)
Fatalities per loss:	17,1
Fatalities per aircraft:	3,1
Last hull loss:	22.SEP.2008 (0 fatalities)
Worst hull loss:	01.JUL.1994 (80 fatalities)

Operator Statistics: Myanmar Airways

Founded (begin of ops):	1948 (as Union of Burma Airways)
No. of hull losses:	30
No. of fatalities:	419
Last hull loss:	02.JUL.1999 (8 fatalities)
Worst hull loss:	11.OCT.1987 (49 fatalities)
No of aircraft:	8 (now 7)
Average fleet age:	16,4 years

Logo:



Worldmap:



ACCIDENT AIRCRAFT HISTORY

Fokker 28-4000, XY-ADW, c/n 11114

first flight:	Fokker	14.03.1977	PH-EXU
delivered to:	Burma AW Corp.	30.06.1977	XY-ADW
renamed:	Myanmar Airways	01.04.1989	XY-ADW

[Order a detailed safety Check of Myanmar Airways in the Media Section](#)

[Link: http://www.jacdec.de/media/ASC/jacdec_airline_safety_check.htm](http://www.jacdec.de/media/ASC/jacdec_airline_safety_check.htm)

¹ NOTE: No part of this publication may be reproduced or transmitted for commercial usage in any form or by any means or by any information retrieval system without written permission from the JACDEC© company. The information herein includes unofficial information and should be treated as this. Editors cannot be held responsible for any errors or omissions caused by any information source mentioned herein.